



Tech Tip

December 2024



Link Low Superheat Alert


Link System will report multiple low Superheat alerts on the indoor EEV. There are 5 steps in clearing this error up.

1. Make sure Hub has been updated to 8.01 software or higher.
2. Using the tech app (shown to the right) or the UX360 put the unit in charge mode cooling for 5 minutes.
3. Do indoor EEV test open
4. Do indoor EEV test closed
5. Put the unit in Charge mode heating for 5 minutes.

Once all the steps are complete put the system back in normal operations.

If the system controller (HUB) is not on 8.01 please make sure to update the software before moving forward with these steps.

[Trane Residential LMS - EEV Troubleshooting](#)



Field Service Representative Contact

1-844-FL- TRANE
1-844-358-7263