



# A2L Tech Tip




## Software: The Key to Link Success

New A2L Communicating LINK air handlers have software that may be newer than the software currently loaded on controllers that are in inventory, or part of stocking orders. Software needed is greater than version 9.0

Current Stock of TLINK360A2VVUF **F** Must be updated in order for the controller to see the new A2L Link air handlers.

It takes minutes to download/upload the software to link- *but it takes Link 3+ hours to apply it.* System will not operate until the update is applied.

A manual Software Upgrade must be completed through the Tech App. Sign-in to the app is **REQUIRED**. Download 9.0 SW and push the update to the controller.



**Field Service Representative Contact**

Trane® Technician

1-844-358-7263



Symbio® Service & Installation