




Tech Tip

July 2025

5HPL50 start up with P8 Error

During installation if the error code shows up on start up it means the unit is outside of the operational range.

Per the manual it states SOV energizes in heating. We have found that when this error code pops up on start up, Change the energizing of the SOV to cooling and this will correct the issue.



Field Service Representative Contact

Trane® Technician

1-844-358-7263



Symbio® Service &
Installation